

In-Production Photo Report for

Enforcer PUC Pumper


Farmington Fire Rescue, ME

Job# 39935

Status as of April 03, 2026

In this report your cab and body were merged with the frame at the start of initial apparatus assembly followed by the start of final assembly. In the next report final assembly may continue.






DSC02600



DSC02601




DSC02602



DSC02603




DSC02604



DSC02605



DSC02606




DSC02608




DSC02609



DSC02610



DSC02611



DSC02612



DSC02613



DSC02614



DSC02615



DSC02616



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company