

In-Production Photo Report for

Enforcer Pumper

Saugus Fire Department, MA

Job# 40304

Status as of June 05, 2026

In this report your cab began initial assembly, the frame build began, the pump house completed initial assembly, and the body completed fabrication and began the paint process with metal finishing. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may remain staged, and the body may begin the paint process.





DSC01169



DSC01170



DSC01171



DSC01172



DSC01173



DSC01174




DSC01098



DSC01099



DSC01100



DSC01101



DSC01102



DSC01103



DSC01104



DSC01105




DSC01106



DSC04104



DSC04105



DSC04106



DSC04107



DSC04108



DSC04894



DSC04895



DSC04896



DSC04897



DSC04898



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company