

In-Production Photo Report for

Enforcer Pumper

Berlin Fire Department, NH

Job# 40661

Status as of August 21, 2026

In this report your cab began initial assembly, the frame build began, the pump house was painted then staged to continue initial assembly, and the body began the paint process with metal finishing. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may continue through paint.





DSC01063



DSC01064




DSC01065



DSC01066



DSC01067



DSC01107



DSC01108




DSC01109



DSC01110



DSC01111



DSC01112



DSC01113



DSC01114



DSC01115



DSC01116



DSC01117




DSC01118



DSC04039



DSC04040



DSC01848



DSC01849



DSC01850



DSC01851



DSC01852



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company