

In-Production Photo Report for

Enforcer PUC Pumper


Bangor Fire Department, ME

Job# 41459

Status as of April 10, 2026

In this report your cab was merged with the frame followed by body installation at the start of initial apparatus assembly. In the next report your apparatus may complete initial assembly and begin final assembly.






DSC02417



DSC02418



DSC02419




DSC02420



DSC02421




DSC02422



DSC02423



DSC02424



DSC02425



DSC02426




DSC02427




DSC02428



DSC02429



DSC04446



DSC04447



DSC04448



DSC04449




DSC04450



DSC04451



DSC04452



DSC04453



DSC04454



DSC04455



DSC04456



DSC04457



DSC04458



DSC04459



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company