

In-Production Photo Report for

Velocity Pumper

Londonderry Fire Department, NH

Job# 42152

Status as of August 07, 2026

In this report your cab continued the paint process, the pump house was painted then staged to continue initial assembly, and the body completed fabrication. In the next report your cab may complete the paint process, the pump house may continue initial assembly, and the body may remain staged to begin the paint process.





DSC01789



DSC01790



DSC01791



DSC01792



DSC01793




DSC04018



DSC04019



DSC04020



DSC04581



DSC04582



DSC04583



DSC04584



DSC04585



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company