

# In-Production Photo Report for

Velocity Pumper

Londonderry Fire Department, NH


Job# 42152

---

Status as of August 21, 2026

In this report your cab began initial assembly, the frame build began, the pump house was staged to continue initial assembly, and the body continued through paint. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may continue the paint process.





DSC01073



DSC01074



DSC01075



DSC01076



DSC01077



DSC01129



DSC01130



DSC01131



DSC01132



DSC01133



DSC01134



DSC01135



DSC01136



DSC01137



DSC01138



DSC04028



DSC04029




DSC04030



DSC04031



DSC04032



DSC04423



DSC04424



DSC04425



DSC04426



DSC04427



# ALLEGIANCE<sup>TM</sup>

## FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company