

In-Production Photo Report for

Velocity Pumper

Londonderry Fire Department, NH

Job# 42153

Status as of August 14, 2026

In this report your cab continued the paint process, the pump house was staged to continue initial assembly, and the body was fabricated then staged. In the next report your cab may continue through paint, the pump house may be painted then staged to continue initial assembly, and the body may remain staged to begin the paint process.





DSC02577



DSC02578



DSC02579



DSC02580



DSC02581



DSC04020



DSC04021




DSC04022



DSC04023



DSC04024



DSC04468



DSC04469



DSC04470



DSC04471



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company