

In-Production Photo Report for

Velocity Pumper


Londonderry Fire Department, NH

Job# 42153

Status as of August 28, 2026

In this report your cab began initial assembly, the frame build began, the pump house was queued to continue initial assembly, and the body began the paint process with metal finishing. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may continue through paint.





DSC01091



DSC01092



DSC01093



DSC01094



DSC01095



DSC01021



DSC01022



DSC01023



DSC01024



DSC01025



DSC01026



DSC01027



DSC01028



DSC01029



DSC01030




DSC04041



DSC04042




DSC04043



DSC04044



DSC04045



DSC02912



DSC02913



DSC02914



DSC02915



DSC02916



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company