

In-Production Photo Report for

Velocity Pumper

Londonderry Fire Department, NH


Job# 42153

Status as of September 03, 2026

In this report your cab completed initial assembly, the frame build continued, the pump house completed initial assembly, and the body continued through paint.

In the next report your cab may be staged, the frame build may continue, the pump house may remain staged, and the body may continue the paint process.





DSC01052



DSC01053



DSC01054



DSC01055




DSC01056



DSC01057



DSC01058



DSC01346



DSC01347



DSC01348



DSC01349



DSC01350



DSC04009



DSC04010



DSC04011



DSC04012



DSC04013



DSC02416



DSC02417



DSC02418



DSC02419



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company