

# In-Production Photo Report for

Arrow XT Pumper

Nashua Fire Department, NH


Job# 39937

---

Status as of April 10, 2026

In this report your cab completed paint, the frame build began, the pump house began initial assembly, and the body completed the paint process. In the next report your cab may begin initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may remain staged to begin initial assembly.






DSC02043



DSC02044



DSC02045



DSC02159



DSC02160




DSC02161



DSC02162



DSC02163



DSC04079



DSC04080



DSC04081



DSC04541



DSC04542



DSC04543



DSC04544



DSC04545



# ALLEGIANCE<sup>TM</sup>

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company