

# In-Production Photo Report for

Arrow XT Pumper

Falmouth Fire & Rescue Department, MA


Job# 40181

---

Status as of June 19, 2026

In this report your cab continued initial assembly, the frame build continued, the pump house completed initial assembly, and the body began the paint process. In the next report your cab may complete initial assembly, the frame build may continue, the pump house may remain staged, and the body may continue through paint.





DSC01067



DSC01068



DSC01069



DSC01070



DSC01071




DSC01105



DSC01106



DSC01107



DSC01108



DSC01109



DSC01110



DSC01111




DSC01112



DSC01113



DSC04119




DSC04120




DSC04121




DSC04122




DSC01954



DSC01955



DSC01956



DSC01957



# ALLEGIANCE<sup>TM</sup>

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company