

# In-Production Photo Report for

Arrow XT Pumper

Falmouth Fire & Rescue Department, MA

Job# 40181


---

Status as of June 26, 2026

In this report your cab was merged with the frame while assembly continued, the pump house was staged, and the body completed the paint process. In the next report the pump house may be merged with the chassis while the body may begin initial assembly.

**Due to limited staffing and the Pierce facilities 4<sup>th</sup> of July shut down next week, your next scheduled report is week ending July 11, 2026.**





DSC01319



DSC01320



DSC01321



DSC01322



DSC01323



DSC01324



DSC01325



DSC01326



DSC01327



DSC01328




DSC01329



DSC01330




DSC01331



DSC01332



DSC01333



DSC01265



DSC01266



DSC01267



DSC01268



DSC01239



DSC01240



DSC01241



DSC01242



DSC01243



DSC01244



# ALLEGIANCE<sup>TM</sup>

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company