

In-Production Photo Report for

Enforcer Pumper


Saugus Fire Department, MA

Job# 40304

Status as of May 15, 2026

In this report your cab continued the paint process while the pump house structure was fabricated. In the next report your cab may continue through paint while the pump house structure may remain staged.





DSC03293



DSC03294



DSC03295



DSC03296



DSC03297



DSC04067



DSC04068



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company