

In-Production Photo Report for

Enforcer Pumper

Berlin Fire Department, NH

Job# 40661

Status as of July 31, 2026

In this report your cab continued through paint while the pump house began initial assembly. In the next report your cab may continue the paint process while the pump house may continue initial assembly.





DSC01930



DSC01931



DSC01932



DSC01933



DSC01934



DSC04053



DSC04054



DSC04055



DSC04056



DSC04057



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company