

In-Production Photo Report for

Saber Pumper


Dunns Corners Fire Department, RI

Job# 41386 : PWO# 32424873

Status as of June 05, 2026

In this report your cab completed fabrication and began the paint process, the pump house began initial assembly, and the body began in paint. In the next report your cab may continue through paint, the pump house may be painted then continue initial assembly, and the body may complete the paint process.





DSC07260



DSC07261



DSC07262



DSC07263



DSC07264



DSC07297



DSC07298



DSC07299



DSC07300



DSC07301



DSC07251



DSC07252



DSC07253



DSC07254



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company