

In-Production Photo Report for

Saber Pumper


Dunns Corners Fire Department, RI

Job# 41386 : PWO# 32424873

Status as of June 12, 2026

In this report your cab completed paint, the pump house was staged, and the body the paint process. In the next report your cab and body may remain staged to begin initial assembly while the pump house may be painted then continue initial assembly.





DSC07177



DSC07178




DSC07179



DSC07180



DSC07181



DSC07010



DSC07011




DSC07012



DSC07013



DSC07014



DSC07041



DSC07042



DSC07043



DSC07044



DSC07045



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company