

In-Production Photo Report for

Kenworth Tanker


Oxford Fire Department, MA

Job# 44144 : PWO# 34176779

Status as of August 07, 2026

In this report chassis prep continued, the pump house and the tank remained staged, and the body completed initial assembly. In the next report chassis prep may continue, the pump house may continue initial assembly, and the tank and the body may remain staged.





DSC06862



DSC06863



DSC06864



DSC06865



DSC06866



DSC06070



DSC06071



DSC06072



DSC06073



DSC06074



DSC06145



DSC06146



DSC06147



DSC06148



DSC06149



DSC06185



DSC06186



DSC06187



DSC06188



DSC06189



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company