

# In-Production Photo Report for

Kenworth Tanker

Oxford Fire Department, MA


Job# 44144 : PWO# 34176779

---

Status as of August 14, 2026

In this report your chassis was staged, the pump house continued initial assembly, and the tank and the body remained staged. In the next report your chassis may continue preparations for fire and emergency use, the pump house may continue initial assembly, and the tank and the body may remain staged.





DSC06688



DSC06689



DSC06690



DSC06691




DSC06692



DSC06693



DSC06280



DSC06281




DSC06282



DSC06283



DSC06284



DSC06175



DSC06176




DSC06177



DSC06178



DSC06179



DSC06070



DSC06071



DSC06072



DSC06073



DSC06074



# ALLEGIANCE<sup>TM</sup>

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company