

In-Production Photo Report for

Kenworth Tanker


Oxford Fire Department, MA

Job# 44144 : PWO# 34176779

Status as of August 28, 2026

In this report chassis prep continued, the pump house continued initial assembly, and the tank and the body were staged. In the next report the chassis may continue preparations for fire and emergency use, the pump house may complete initial assembly, and the tank and the body may be staged.






DSC06285



DSC06286




DSC06287



DSC06288



DSC06289




DSC06005



DSC06006



DSC06007



DSC06008



DSC06009



DSC06215



DSC06216



DSC06217



DSC06218



DSC06219



DSC06085



DSC06086



DSC06087



DSC06088



DSC06089



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company