

In-Production Photo Report for

Kenworth Tanker

Oxford Fire Department, MA

Job# 44144 : PWO# 34176779

Status as of July 24, 2026

In this report chassis prep continued, the pump house continued initial assembly, the tank was having chevron applied, and the body completed fabrication and paint. In the next report your chassis may continue preparation for fire and emergency use, the pump house may continue initial assembly, the tank may be staged, and the body may remain staged to begin initial assembly.



ification - Restricted
M FORM
Sheet

QSF10-0836
Effective Date: 05/12/23
Page 1 of 2

Job #: 44144-1
211356
D. MA
Christina
& Rescue

☐ Yes ☒ No
☐ Yes ☒ No

DSC06343



DSC06344



DSC06345



DSC06346



DSC06347



DSC06021



DSC06022



DSC06023



DSC06024



DSC06025



DSC06378



DSC06379



DSC06380



DSC06381



DSC06382



DSC06165



DSC06166



DSC06167



DSC06168



DSC06169



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company