

In-Production Photo Report for

Kenworth Tanker


Oxford Fire Department, MA

Job# 44144 : PWO# 34176779

Status as of July 31, 2026

In this report the chassis continued preparation for fire and emergency use, the pump house was staged, the tank completed chevron application, and the body remained staged. In the next report chassis prep may continue, the pump house may continue initial assembly, the tank may be staged, and the body may begin initial assembly.





DSC06263



DSC06264



DSC06265



DSC06266



DSC06267



DSC06046



DSC06047



DSC06048



DSC06049



DSC06050



DSC06163



DSC06164



DSC06165



DSC06166



DSC06167



DSC06138



DSC06139



DSC06140



DSC06141



DSC06142



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company