

In-Production Photo Report for

Saber Pumper


Scarborough Fire Department, ME

Job# 44414 : PWO# 34383489

Status as of April 03, 2026

In this report your cab remained staged, the pump house continued initial assembly, and the body continued the paint process. In the next report your cab may begin the paint process, the pump house may be painted then staged to continue initial assembly, and the body may complete paint.





DSC07230



DSC07231



DSC07163



DSC07164




DSC07165



DSC07166



DSC07167



DSC07140



DSC07141



DSC07142



DSC07143



DSC07144



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company