

In-Production Photo Report for

Saber Pumper


Scarborough Fire Department, ME

Job# 44414 : PWO# 34383489

Status as of April 10, 2026

In this report your cab began the paint process, the frame build began, the pump house continued initial assembly, and the body completed paint. In the next report your cab may continue through paint, the frame may be staged, the pump house may be painted then continue initial assembly, and the body may remain staged to begin initial assembly.





DSC07164



DSC07165



DSC07166



DSC07167



DSC07168



DSC07574



DSC07575




DSC07576



DSC07577




DSC07578



DSC07015



DSC07016




DSC07017



DSC07018



DSC07019



DSC07169



DSC07170



DSC07171



DSC07172



DSC07173



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company