

In-Production Photo Report for

Saber Pumper


Scarborough Fire Department, ME

Job# 44414 : PWO# 34383489

Status as of April 17, 2026

In this report your cab completed the paint process, the frame was unavailable, and the pump house and the body were staged. In the next report your cab may begin initial assembly, the frame may be available to photograph, the pump house may be painted then continue initial assembly, and the body may begin initial assembly.





DSC07264



DSC07265




DSC07266



DSC07267



DSC07268



DSC07025



DSC07026




DSC07027



DSC07028



DSC07029



DSC07312



DSC07313



DSC07314



DSC07315



DSC07316



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company