

# In-Production Photo Report for

Enforcer Aerial

Swampscott Fire Department, MA

Job# 44936

---

Status as of April 03, 2026

In this report your cab began initial assembly, the frame build continued, the transverse compartment began fabrication, and the body began the paint process. In the next report, your cab may continue initial assembly, the frame build may continue, the transverse may complete fabrication, and the body may continue through paint.





DSC02072



DSC02073




DSC02074



DSC02075



DSC02076



DSC02006




DSC02007



DSC02008



DSC02009




DSC02010



DSC02011



DSC02012




DSC04088




DSC04089



DSC04090



DSC03045



DSC03046



DSC03047



# ALLEGIANCE<sup>TM</sup>

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company