

In-Production Photo Report for

Enforcer Aerial

Swampscott Fire Department, MA

Job# 44936

Status as of May 01, 2026

In this report the transverse and body were merged with the chassis then your apparatus began final assembly.
In the next report final assembly may continue.





DSC02473



DSC02474




DSC02475



DSC02476



DSC02477



DSC02478



DSC02479



DSC02480



DSC02481



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company